

The Board of Pharmacy has received notice of the following product recall. The Board strongly encourages pharmacies to immediately review their quality assurance and recall policies and procedures to determine if any corrective action is required.

This is to inform you of that **Abbott** is initiating a voluntary recall at the Retail level for **FreeStyle Libre 3 and FreeStyle Libre 3 Plus sensors** as an abundance of caution.

Abbott has recently identified that certain FreeStyle Libre 3 and FreeStyle Libre 3 Plus sensors provide incorrect low glucose readings.

72081-01 FreeStyle Libre 3 Sensor Kit Impacted Lots

T60003054	T60003092	T60003159	T60003374	T60003434	T60003547
T60003085	T60003099	T60003160	T60003375	T60003507	T60003564
T60003088	T60003113	T60003271	T60003391	T60003534	T60003628
T60003089	T60003136	T60003284	T60003426	T60003546	T60003646

78768-01 FreeStyle Libre 3 Plus Sensor Kit Impacted Lots

T60002984	T60003366	T60003455	T60003492	T60003560	T60003592
T60002994	T60003369	T60003460	T60003494	T60003562	T60003596
T60002995	T60003377	T60003470	T60003496	T60003563	T60003601
T60002996	T60003378	T60003471	T60003497	T60003567	T60003611
T60003007	T60003379	T60003473	T60003498	T60003568	T60003617
T60003009	T60003384	T60003478	T60003518	T60003570	T60003618
T60003010	T60003398	T60003479	T60003542	T60003573	T60003619
T60003138	T60003400	T60003480	T60003543	T60003575	T60003631
T60003243	T60003404	T60003481	T60003544	T60003576	T60003639
T60003255	T60003446	T60003488	T60003550	T60003585	T60003641
T60003348	T60003449	T60003490	T60003552	T60003589	T60003683
T60003352	T60003454	T60003491			

Abbott has identified and resolved the cause of the issue. The company continues to produce Libre 3 and Libre 3 Plus sensors to fulfill replacement and new orders and does not expect significant supply disruptions.